## <u>Advantex – Mounting Plate Retrofit Chart</u>

| Detex | Von Duprin | Sargent            | Precision          | Dorma<br>Kaba                | Yale | Corbin<br>Russwin |
|-------|------------|--------------------|--------------------|------------------------------|------|-------------------|
| BP-1* | 98/99      |                    |                    |                              |      |                   |
| BP-3  |            | 8800<br>(see note) | 2100<br>(see note) | 9300/<br>F9300<br>(see note) |      |                   |
| BP-5  |            |                    |                    |                              | 7100 | ED5200            |

Advantex mounting plates offer the ability of retrofitting the rim device using existing door preps of manufacturers listed above. *Applies to Detex wide stile Advantex Rim Devices*, without vertical rods.

Note: Backplate hole alignment may be off by up to 1/16"

\*BP-1 ships standard with Advantex 10 Series devices unless otherwise specified

